


GENWAL RESOURCES, INC.
P.O. BOX 1420
HUNTINGTON, UTAH 84528

ANNUAL REPORT - 1994




ACT 015-032




GENWAL
RESOURCES, INC.

P.O. Box 11420 • 195 North 100 West • Huntington, Utah 84528
Telephone (801) 687-9813 • Fax (801) 687-9784



April 12, 1995

Mr. Daron Haddock
Permit Supervisor
Division of Oil, Gas and Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203



Dear Daron:

ACT/015/032 #6

The Annual Report for Genwal Resources, Inc. Crandall Canyon Mine is attached. We have included a copy of our water quality data on a computer disk in the FoxPro format. If you need additional information or a different format for the water quality data please let us know.

Sincerely,

Randolph B. Gainer, P.G.
Environmental Manager

WATER
MONITORING

1

CLIMATOLOGICAL
DATA

2

SUBSIDENCE
MONITORING

3

VEGETATION
DATA

4

IMPOUNDMENT
CERTIFICATION

5

ACID BASE
POTENTIAL
SAMPLE DATA

6


MISCELLANEOUS

7

RECEIVED

APR 13 2005

DIVISION OF OIL
GAS & MINING PRICE UTAH



8

COAL MINING AND RECLAMATION OPERATIONS FOR 1994

(Must be submitted to the Division by April 14, 1995)

State of Utah
Department of Natural Resources
Division of Oil, Gas and Mining
3 Triad Center, Suite 350
355 West North Temple
Salt Lake City, Utah 84180-1203
(801) 538-5340

Permittee: Genwal Coal Company
Mine Name: Crandall Canyon
Mailing Address: P.O. Box 1420, Huntington, UT 84528
Company Representative: Randolph B. Gainer
Resident Agent: Randolph B. Gainer
Permit Number: ACT/015/032
MSHA ID Number: 42-01715
Date of Initial Permanent Program Permit: 02/27/88
Date of Permit Renewal: 05/13/98
Quantity of Coal Mined (tonnage) 1994: 1,546,744

Attach Updated Mine Sequence Map(s) showing mine development through December 31, 1994.
(Same as Lease Royalty Payment Map and/or MSHA Progress Map)

All monitoring activities during the report period to be submitted with this report (including, but not limited to):













A. General

1. Discuss anomalies, missing data and monitoring changes made throughout the year.
2. Summarize any corrective actions and the results that may have occurred during the year.

**B. Water Monitoring Data:
Groundwater Summary**

1. Mine Discharge
 - a. Summarize the total annual discharge from mine water discharge points and breakdown on a monthly basis for each site.
 - b. Discuss the past five years of data comparing changes in discharge. (Include in the discussion elements encountered during the year such as mining rate, location of faults or large in-mine flows during the year.)
 - c. Discuss trends, if existent, and exceedence in water quality parameters. A correlation with flow could provide additional information.

GENWAL COAL COMPANY, INC.
CRANDALL CANYON MINE
ID# 42-01715

	<u>PENCIL #</u>	<u>COLOR</u>		<u>TONNAGE</u>
January	743 1/2	Rose		<u>134,866</u>
February	735 1/2	Lemon Yellow		<u>112,487</u>
March	740 1/2	Skyblue		<u>135,410</u>
April	737	Orange		<u>108,803</u>
May	738 1/2	Light Green		<u>143,085</u>
June	734 1/2	Light Grey		<u>153,494</u>
July	742 1/2	Lavender		<u>111,227</u>
August	745 1/2	Terra Cotta		<u>126,479</u>
September	740	Blue		<u>122,843</u>
October	744	Red		<u>127,220</u>
November	736	Yellow Orange		<u>132,153</u>
December	739	Green		<u>138,677</u>